Interior Wall Coverings and Finishes Version 1-2				
Classification:	Interior Walls			
Definition:	The finished or unfinished surface that provides a vertical separation between rooms or spaces and may provide security/privacy, sound proofing, climate control, and fire protection			
Please Note:	For the purpose of this inspection, any interior wall that adjoins an outside area will be evaluated as an exterior wall.			
Name Variants:	Partition			
Most Common Materials:	Plaster, Drywall, Paneling, Paint, Wallpaper, Brick, Stone, Tile, Stucco, Wood			
Most Common Components:	Covering, finish, molding, baseboards			

Location & Inspection of Wall Coverings and Finishes						
Abilities or Knowledge Needed:	<ul> <li>Visual acuity for location &amp; inspection</li> <li>Mobility for access to all areas of the property</li> <li>Ability to bend, stoop, and kneel</li> </ul>					
Tools for Location &	Useful:	None				
Inspection	Required:	None				
Common Locations:	Unit/Inside:	Dining rooms, living rooms, kitchens, bathrooms, bedrooms, closets, hallways, other interior spaces				
How to Locate:	Visual Observation:	Look in common locations between the floor and ceiling				
Possible Deficiencies:	Deficiency 1: Deficiency 2:	Interior wall has any unintended hole that penetrates the wall surface Interior wall has any unintended penetrations through a wall assembly				

Deficienc	<u>y 1</u> : Interior	wall has any unintended hole that	
	penetrat	tes the wall surface	
Rationale:	Health, Indirect: Holes in a wall can expose residents to potential pollutants, allergens, or hazards (such as dust, insulation, lead dust, wiring) within the wall cavity. Holes in a wall can allow entry of vermin into a room, which can then negatively impact resident health.		
Health and Safety Determination:	This is a standard health and safety issue requiring correction within 30 days.		
How to Inspect:	Visual Observation:	Look at wall for presence of hole(s) and determine if the hole penetrates only the wall surface (does not penetrate to adjoining space)	
	Action:	Measure hole (or a number of unintended holes taken cumulatively) to determine if it measures 6x6 inches or greater.	
Record deficiency if:	Hole (or a number of holes taken cumulatively) measures 6x6 inches or greater.		

<u>Deficiency 2</u> : Interior wall has any unintended penetrations							
through a wall assembly							
Rationales:	Health, Indirect: Holes in a wall can expose residents to potential pollutants, allergens, or hazards (such as dust, insulation, lead dust, wiring) within the wall cavity. Holes in a wall can allow entry of vermin into a room, which can then negatively impact resident health.						
	Security, Indirect: If the hole in the wall connects to another unit, this could allow unsecured access to the unit.						
	Privacy, Direct: If the hole in the wall connects to another unit, this can allow residents to see into each other's units. If the wall is in a bathroom or bedroom, even if the hole connects to the same unit, this would interfere with privacy.						
	Corrective Maintenance, Indirect: It is reasonable to expect tenants to report holes that penetrate through walls all the way to the space on the other side of the wall and for facilities management to prioritize a work order response to fix that deficiency.						
Health and Safety Determination:	This is a standard health and safety issue requiring a correction, remedy, or act of abatement within 30 days.						
How to Inspect:	Visual Observation:	Look at wall for presence of any hole and determine if the hole penetrates to the adjoining space.					
	Action:	Look to see if any hole penetrates to the adjoining space.					

Any sized hole penetrates to the adjoining space.

Record

deficiency if:

## Interior Wall Coverings and Finishes, Version 1-2 (27 Dec 2019)

Summary of Changes (from Version 1)

• The **Rationales** and the **Health and Safety Determinations** have been updated, following in-house review and public comment.